Totally Integrated Automation Portal
--------------------------------------

## Sorting / PLC\_1 [CPU 314C-2 PN/DP] / PLC tags

## Default tag table [18]

N	lame	Data type	Address	Retain	Acces-	Writa-	Visi-	Supervision	Comment
		3-1			sible from HMI/O	ble from HMI/O PC UA	ble in HMI engi-		
<b>1</b>	Raise Stopper (B3)	Bool	%10.2		True	True	True		
<b>1</b>	Magazine Level (B4)	Bool	%10.3		True	True	True		
<b>1</b>	Left Limit Sensor (IL)	Bool	%I1.3		True	True	True		
•	Right Limit Sensor (IR)	Bool	%I1.4		True	True	True		
<b>40</b>	Start	Bool	%I2.2		True	True	True		
<b>1</b>	Lower Stopper (M1)	Bool	%Q0.0		True	True	True		
<b>1</b>	Sort (M2)	Bool	%Q0.2		True	True	True		
<b>1</b>	Forward (OR)	Bool	%Q1.0		True	True	True		
<b>1</b>	Inching Mode (QS)	Bool	%Q1.2		True	True	True		
<b>1</b>	State 2 Transition	Bool	%M0.0		True	True	True		
<b>1</b>	State 3 Transition	Bool	%M0.1		True	True	True		
<b>•</b>	State 4 Transition	Bool	%M0.2		True	True	True		
<b>1</b>	State 5 Transition	Bool	%M0.3		True	True	True		
<b>40</b>	State 6 Transition	Bool	%M0.4		True	True	True		
<b>1</b>	State 1 Transition	Bool	%M0.5		True	True	True		
<b>1</b>	Timer	Bool	%M0.6		True	True	True		
<b>1</b>	Timer 2	Bool	%M0.7		True	True	True		
<b>1</b>	Trig Mem	Bool	%M1.0		True	True	True		