


2:06 ↗



Card



Lock



Copy •• 9774



Explore offers
Instant discounts >

Spending




Insights & activity


\$13 in Nov >



2:06 ↗



X



Midas 20 Egg Har Hin

May 20 at 12:34 PM

\$1,101.36

Transaction details

✓ Complete

Purchase from Midas 20 Egg Har Hin

\$ Payment method

Black Metal Card 9774

📄 On statement as

MIDAS 20 EGG HAR 3109 HIN

What you can do

⟳ View Round Up receipt >



Filter


2

7

26

1

Midas Egg Harbor
 3109 Hingston Ave
 Egg Harbor, NJ 08234
 Trust The Midas Touch
609.900.6475 ☎
midaswestberlin@gmail.com ✉



RO# 0002663 5/20/2025
DEVON BARBAR
 2019 VOLKSWAGEN
 PASSAT
 VIN:
 1VWLA7A36KC002247
 License: F35VLP
 Mileage: 95789




Service Advisor
PERRY HERMAN

Midas Closer Look Vehicle Check

Exterior

Body & Glass: Visual Inspection OK

Images:



Exterior Lights: Visual Inspection OK

Technician
KURTIS WASYLKOWSKI

█ EXTERIOR LIGHTS, VISUAL INSPECTION OK

Wipers: Visual Inspection OK

Interior

⚠ Dash Indicator Lights: TPMS Light On "Solid"

- Evaluation Required

Images:




Under Hood

Horn: Operating


Engine Air Filter: Visual Inspection OK

Images:



◆ Cabin Air Filter: Beyond Service Interval -
Replacement Suggested

Images:



Battery / Cables: Visual Inspection OK


Images:



Hoses: Visual Inspection OK

Belts (except timing belt): Visual Inspection OK

Images:



Windshield Washer Fluid: Reservoir Full


Engine Oil: Dipstick Within Specifications

Power Steering Fluid: Dipstick Within Specifications

Transmission / Transaxle Fluid: Dipstick Within Specifications

Coolant: Beyond Service Interval - Fluid Exchange Suggested

Images:






Under Vehicle

- Exhaust System: Visual Inspection OK
- Differential / Transfer Case: Visual Inspection OK
- Steering System: Visual Inspection OK
- Shocks / Struts Front: Visual Inspection OK

Images:



-
- Shocks / Struts Rear: Degraded Ride/Control - Replacement Suggested

Images:




-
- Driveline (CV / Drive Shaft): Visual Inspection OK

Brakes

- Brake Fluid: Beyond Service Interval - Fluid Exchange Suggested

Images:


Images:



Brake Symptom Observed: None at this time

Brake Visual Inspection Front: Visual
Inspection OK

Images:



Brake Visual Inspection Rear: Visual
Inspection OK

Images:



Tire Condition

Tire Size Actual - See Picture: Matches
Placard Specifications

Images:






-
- ◆ LF - Tread Depth: 4/32" - Close To The End Of Useful Life

Images:



-
- ◆ RF - Tread Depth: 3/32" - Close To The End Of Useful Life

Images:



-
- ✓ RR - Tread Depth: 6/32" - Tread Depth Within Guidelines

Images:



-
- ◆ LR - Tread Depth: 4/32" - Close To The End Of Useful Life

Images:





⚠ Tire Inspection Suggestions: Irregular Tread Wear - Evaluation Required

Tire Pressure

LF - Tire Pressure: Matches Placard Specifications

RF - Tire Pressure: Matches Placard Specifications

RR - Tire Pressure: Matches Placard Specifications

LR - Tire Pressure: Matches Placard Specifications

Technician Note

Technician Notes: See Notes Below

Comments:

rec 4 tires and alignment by edgewear and tread depth
rec cabin filter by mileage rec coolant and brake flush by mileage rec rear shocks by mileage rec tune up by mileage rec fuel service by mileage front and rear end tight, caster out 1 degree not adjustable

Images:



