

MAIN
Initialization
NO
Wait for interrupt
(will be from UART)
YES
UART receives
byte
Python GUI sends
data to CyBot, causing
an interrupt
'M"
Check what byte
was recieved
'F'
CLIFF/BUMP SENSORS
SCAN
move servo
from 0 to 180
and read IR
values from ADC
at each angle
'n'
'A'
'D'
move_forward
CyBot moves forward
while checking the
bump and cliff
sensors. Will halt if
cliff or bump is
detected
play music using
cybot music module
turn_left
turn_right
Send values to
GUI through UART
MUSIC
MODULE
WHEELS
Python GUI receives
values and plots polar
graph