

Hydraulic Press B200 PDF Manual

Synthetic demo data. Not a real manufacturer manual.

Device Name: Hydraulic Press B200

Device Model: B200

Fault Code Table

F01 Hydraulic pressure insufficient. Possible causes include low oil level, pump wear, blocked filter, or pressure

Troubleshooting steps: stop the press, release stored pressure, inspect oil level, check filter, verify pump noise,

Safety reminder: do not open hydraulic lines before pressure is released.

Safety Rules

Lock out the main power, release hydraulic pressure, support the slider mechanically, and confirm pressure gauge

Live maintenance, pressurized disassembly, oil leakage with unstable pressure, or safety interlock failure require

Parameters

Rated pressure range: 8-12 MPa.

Oil temperature range: 20-60 C.

Maintenance Flow

Inspect oil level weekly. Replace hydraulic filter every 90 days. Record pressure trend and leakage status.