

Sample Material: PEO/AgNW Composite

Preparation: Dissolve PEO in deionized water at 5 wt%.

Add AgNW dispersion and sonicate for 30 min at 100W.

Cast film and cure at 80 degC for 2h.

Results: Electrical conductivity ~5000 S/cm (Figure 3).

Tensile strength 15 MPa (Table 3).

Table 2: Composition - 25 wt% AgNW in PEO matrix.