Fault Tree Analysis

Chapter 15



1

3

What is FTA?

- A method of calculating the expected frequency (or probability) of an unwanted event.
- □ Use for cases when several different kinds of causes exist.

2

4

Fault Tree Analysis Root Causes Initiating Mechanism (Event) Before TTO After

Application of FTA

- Calculating failure rate of a sub-assembly with multiple components
 - ⇒ Such as pressure sensor system, or shutdown valve assembly
- □ Calculating frequency of an unwanted event with a complex set of causes ⇒ e.g. Air Traffic Control Failure
- Finding a single point of failure that could shut down a whole system.



5


Definitions

□ Failure

- ⇒Occurrence of a basic component failure
- ⇒No further breakdown


□ Fault

- ⇒Occurrence of an undesired state for a component, subsystem or system
- ⇒Can be further broken down




6

Failure and Fault Example



7



Node Types:
Gate Event
Conditional Events

OR OR and

Transfer Events

Basic Events

10

12

FTA Building Blocks

9

11

Logical Connection Between Events

AND: The resulting output event requires the simultaneous occurrence of all input event.
 e.g. Event C will occur only if both events A and B occur simultaneously, which is represented (for independent events, A, B) by

 $A \cdot B = C$




OR: The resulting output event requires the occurrence of *any individual* input event e.g. C will occur if either A or B occurs, which is represented (when A, B each has low probability of occurring) by




A + B = C

Flat Tire Flat Tire Flat Tire Flat Tire Top Level Event Logic Gate Intermediate Events Logic Gate Defective Tire Tire Road Debris Basic Events (Root Causes)




13




Symbol Gate Type Description The output occurs only if all of the inputs occur together. AND Gate $P = P_A \cdot P_B = P_A P_B$ (2 input gate) $P = P_A \cdot P_B \cdot P_C = P_A P_B P_C$ (3 input gate) The output occurs only if at least one of the inputs occurs. $\begin{array}{l} P = P_{\rm A} + P_{\rm B} - P_{\rm A} P_{\rm B} \quad (2 \text{ input gate}) \\ P = (P_{\rm A} + P_{\rm B} + P_{\rm C}) - (P_{\rm AB} + P_{\rm AC} + P_{\rm BC}) \quad + \ (P_{\rm ABC}) \quad (3 \text{ input gate}) \end{array}$ The output occurs only if all of the inputs occur together, Priority and A must occur before B. The priority statement is contained in the Condition symbol. AND $P = (P_A P_B) / M!$ Gate Given $\lambda_A \approx \lambda_B$ and N = number of inputs to gate The output occurs if either of the inputs occurs, but not both. The exclusivity statement is contained in the Exclusive condition symbol. Gate $P = P_A + P_B - 2(P_A P_B)$ 0 The output occurs only if the input event occurs and the Inhibit attached condition is satisfied. $P = P_A \cdot P_Y = P_A P_Y$ Ch 15 page 246 Figure 15.5

14



15



Common Cause

Common cause events should be added at the top level using an OR gate

Sitcks

Valve System Fails

OR

AND


Valve A

Sticks


Valve A

Sticks

FTA Example 1




Oct-20



21

23



Cut Sets


- □ A set of events that together cause the tress Top Undesired Event (UE) to occur.
- Minimal Cut Set: the minimum number of events that can still cause the top event to occur.
- □ CS Order: number of items in a CS
 ⇒ One-order CS is a single-point failure (SPF)
- Critical Path: highest probability CS
- MOE: multiple occurring event

22

24

FTA Example 2


Oct-20




 $P_{G4}=P_B+P_C-P_BP_C$ $P_{G4}=1.0 \times 10^{-4} + 2.0 \times 10^{-4} - (1.0 \times 10^{-4}) (2.0 \times 10^{-4})$ P_{G4}=3.0 x 10⁻⁴ $P_{\text{G5}}=P_{\text{E}} \cdot P_{\text{F}}$ $P_{\text{G5}}=1.0 \times 10^{-3} \times 2.0 \times 10^{-3}$ $P_{G5}=2.0 \times 10^{-6}$ $P_{\rm G2}\!\!=\!\!P_{\rm A}+P_{\rm G4}-P_{\rm A}P_{\rm G4} \ P_{\rm G2}\!\!=\!\!9.0\times 10^{-6}+3.0\times 10^{-4}-(9.0\times 10^{-4})~(3.0\times 10^{-6}) \ P_{\rm G2}\!\!=\!\!3.9\times 10^{-4}$ $P_{\rm G3} = P_{\rm D} + P_{\rm G5} - P_{\rm D}P_{\rm G5}$ $P_{\rm G3} = 1.0 \times 10^{-9} + 2.0 \times 10^{-6} - (1.0 \times 10^{-9}) (2.0 \times 10^{-6})$ $P_{\rm G3} = 2.0 \times 10^{-6}$ $P_{\text{G1}} = P_{\text{G2}} \cdot P_{\text{G3}}$ $P_{\text{G1}} = 3.9 \times 10^{-4} \times 2.0 \times 10^{-6}$ P_B=1.0 x 10⁻⁴ P_C=2.0 x 10⁻⁴ P_E=1.0 x 10⁻³ P_F=2.0 x 10⁻³ P_{G1}=7.8 x 10⁻¹⁰

FTA Example 3

26




27



Determine the Cut Sets Overpressure of Reactor Top event Failure of Alarm Failure of Emergency Solenoid Pressure switch 1 Switch 2 Valve Failure Failure

30



Overpressure P=0.0702 Failure of Alarm Failure of Emergency Shutdown Indicator Switch 2 switch 1 P=0.04 P=0.13 P=0.13P=0.34

