





Collaborative Bachelor's Degree Program of Fire Protection and Safety Engineering Technology between Southwest Jiaotong University and Oklahoma State University, U.S.A.



FPST 2023 Industrial and Occupational Safety

Control of Hazardous Energy (lockout/tagout) 29 CFR 1910.147

1



Injury Prevention



- When people are working around moving equipment, they are protected by one of two methods
 - · Machine Safeguarding
 - 29 CFR 1910 Subpart O
 - · Controlling Hazardous Energy
 - 29 CFR 1910.147 Control of Hazardous Energy (lockout/tagout)

2



Definitions




- <u>Lockout</u> The placement of a lockout device on an energy-isolating device to maintain a piece of equipment at <u>zero</u> energy state
- <u>Tagout</u> The placement of a tagout device on an energy-isolating device to indicate a piece of equipment is at a <u>zero</u> energy state

















Lockout vs. Tagout



- 1910.147(c)(2)(ii)
 - If an energy isolating device is capable of being locked out, the employer's energy control program under paragraph (c)(1) of this section shall utilize lockout, unless the employer can demonstrate that the utilization of a tagout system will provide full employee protection as set forth in paragraph (c)(3) of this section
- 1910.147(c)(3)
 - Full employee protection. (i) When a tagout device is used on an
 energy isolating device which is capable of being locked out, the
 tagout device shall be attached at the same location that the
 lockout device would have been attached, and the employer shall
 demonstrate that the tagout program will provide a level of safety
 equivalent to that obtained by using a lockout program.
- 1910.147(d)(4(iii)(A)(A)
 - Where tagout devices are used with energy isolating devices designed with the capability of being locked, the tag attachment shall be fastened at the same point at which the lock would have been attached.

7



Definitions



 Energy Isolating Device – A mechanical device that prevents the release of transmission of energy. Examples are: a manually operated circuit breaker, a disconnect switch, a line valve, a block, and other similar devices.

8



Definitions



Servicing and/or Maintenance — Workplace activities such as constructing, installing, setting up, adjusting, inspecting, modifying, and maintaining or servicing machines or equipment. These activities include lubrication, cleaning, or un-jamming machines or equipment and making adjustment or tool changes when the employee may be exposed to the unexpected energization or startup of the equipment or release of hazardous energy.







The OSHA Standard



OSHA requires the following:

- All power sources must be locked out for servicing or maintenance that is not part of normal production operations;
- Guards or interlock devices, used to protect operators during normal operations cannot be substituted for locks during service or maintenance;

10



The OSHA Standard



- The employer must develop a written energy control program that clearly explains procedures for each piece of equipment with one or more energy sources.
- Employees affected by lockout procedures must be trained.

11		
	Energy Sources	Ą
		Electrical Mechanical Mechanical Mechanical Potential Hydraulic Pneumatic Chemical Thermal







Energy Control Program



- · The written program shall identify:
 - Written energy control procedures for each piece of equipment with one or more energy sources;
 - · Documented employee training; and
 - · Documented periodic inspections.


13



Written Energy Control Procedures



- · Procedures shall include
 - Specific procedural steps for shutting down, isolating, blocking, and securing machines or equipment to control potentially hazardous energy.
 - Specific requirements for testing a machine or equipment to determine and verify the effectiveness of lockout devices and tagout devices and other energy control measures.



ıres 🥸	d		







General



- Energy sources shall be at Zero Energy State (ZES) during lockout or tagout.
- Interlocks, locking of push buttons, selector switches, and other control circuit type devices do not qualify as energy isolation devices for lockout.

16



17



General



- Removing or bypassing guards or other safety devices to do work requires the equipment to be at ZES (lockout) <u>regardless</u> of the task being performed.
- Servicing or maintenance tasks that are <u>not</u> considered part of "normal production operations" require the equipment to be locked out.





A
ABUILT
(家職工)
THE STATE OF THE S

General



During servicing and maintenance that is <u>not</u> part of normal production operations when an employee is required to place any part of their body into an area on a machine or piece of equipment where work is actually performed upon the material being processed (Point of Operation), or where an associated danger zone exists during a machine operating cycle, the machine shall be locked out.

19



General



 Minor tool adjustments, changes or other minor servicing activities taking place during "normal production operations" <u>not</u> requiring guarding or other safety devices to be removed or bypassed do not fall under the scope of lockout or tagout, they are in the scope of alternate procedures or "energy control".

20





PREAMBLE









General



- No employee shall work under the protection of another employee's lockout or tagout.
- Lockout locks shall be used solely for the purpose of locking energy isolating devices and nothing else (e.g. locking toolboxes or personal lockers).


22
















































34



35



Lockout Process




- Preparation for shutdown
 - Determine energy present and equipment needed to obtain zero energy and notify affected employees
- · Machine or Equipment Shutdown
- Machine or Equipment Isolate
- Lockout or tagout device application
- Relieve stored energy
- · Verification of isolation



























Safe Start-up Pro	ocedures	<u>Q</u>
GCK GUT KIT	Step 1: Notify af employe Step 2: Ensure f area is c tools and people Step 3: Remove lockout devices start equipme	ees the clear of d

43



Lock Removal



 Removal of a lock is done only by the authorized employee responsible for it and is never to be bypassed, ignored, or otherwise defeated.

44




Additional Requirements





- · Shift Change
- · Temporary Removal of Lockout
- Annual Evaluation
- Contractor Coordination





































































61



Summary



 When machine guarding is removed or safeties are bypassed to perform servicing and maintenance, the machine must be at zero energy and locked out or tagged out

6	2