




Group 13 - XtremeV - Wiring Diagram












OUT (-)

OUT (+)

8 A 300 W Adjustable Buck Converter

BATTERY (-) O-

BATTERY (+) O-



SONAR1 ULTRASONIC SENSOR