33 What is the purpose of the brushes and the split-ring commutator in a d.c. motor?

A to change the size of the current

B to keep the coil turning in the same direction

C to keep the speed of rotation constant

D to make the output an alternating voltage