
33 The diagram shows the structure of a simple transformer.



Which row shows the correct conditions for the efficiency of the transformer to be as high as possible?

	primary and secondary coils	core
A	thick copper wire	soft iron
B	thin copper wire	soft iron
C	thick iron wire	copper
D	thin iron wire	copper