35 Which metal is used for the core of a transformer?

A aluminium

B copper

C soft iron

D steel