

Stage 6.3 work-zone geometry and transfer diagnostics

States by work zone - 1.8-2.6 mm: train 300, test 78; 2.4-3.2 mm: train 300, test 78; 3.0-3.8 mm: train 561, test 78; 3.4-4.2 mm: train 300, test 78.

