GOVERNMENT OF TELANGANA
BOILERS DEPARTMENT

Office of the Director of Boilers,
H.No.2-2-647/182/A, 3rd Floor,
Above State Bank of India,
Shivam Road, Bagh Amberpet,
Hyderabad – 500 013.

RENEWAL AS BOILER ERECTOR / REPAIRER

IN TELANGANA STATE UNDER INDIAN BOILER REGULATIONS, 1950

* * *

This is to certify that the capacity, capability, Inspection and Quality Management System of

M/s. HARITHA INDUSTRIES (INDIA) PVT. LTD.,
Plot / Sy.No. D No 8-59/3/2 Sy.No 487 PART,
Locality. IDA BOLLARAM ROAD,
Bachupally (Vi),
Bachupally ((M),
Medchal (Di),
500072 (Pin).

Has been evaluated by the Directorate of Boilers and has been granted Renewal under Indian Boiler Regulations,1950 as **Class – II** (Boiler & Steam Pipeline for pressure upto 40 Kg/Cm^2)

This certificate is valid for 2 years i.e upto **03/11/2024**

Validity is subject to the adherence to the quality control prescribed under the provision of the Indian Boiler Regulation,1950

Certificate No. **TS/BE-27/2022**

Date of Issue. **11/11/2022**

SREENIVAS ARAO MULLAPUDI

Digitally signed by SREENIVASARAO MULLAPUDI
DN: c=IN, o=the director of boilers, ou=DIRECTOR OF BOILER, pseudonym=fb9f3c8bfbe3796d58825552f5100eced1e13d37c68f6145fb8de5f19637c7e0, 2.5.4.20=aad80da9735a24662f6c431cf418147bcd42822b4c89e0d7e6a0768aeff55463, postalCode=500013, st=TELANGANA, serialNumber=f0863f2ba06cef66bc5e9c9857025743ca6ecb2687d618d91a64ab097b697f6d, cn=SREENIVASARAO MULLAPUDI
Date: 2022.11.11 15:40:21 +05'30'

DIRECTOR OF BOILERS
TELANGANA STATE, HYDERABAD

INSTRUCTIONS

Internally

1. Any repairer erection/modification of Boiler, Economiser, Steam Pipeline shall be carried out only after obtaining prior written approval from the Director of Boilers, Under section 12 and 13 of the Boilers Act, 1923, Strictly in adherence to the quality control prescribed under the Indian Boiler Regulation 1950.

2. Steam pipeline erection/modification shall be carried out only after obtaining prior approval of steam pipeline layout drawing and welding procedure.

3. Only approved electrodes shall be used in the welding work

4. Clearance from the concerned Inspecting officer shall be obtained at every stage of erection, repairer, modification of Boiler/Economizer and erection of steam pipeline as stipulated under the Indian Boilers Regulation 1950 and its latest amendments

5. All welding works shall be carried out through qualified welders. If any new qualified welders is proposed to be engaged, prior approval shall be obtained from the Director of Boilers.

6. A record in Form-H of welding personnel engaged on welding and repairing of Boiler, Economiser and Steam pipeline should be maintained and produced to the inspecting authority, inspecting officer on demand.

7. Any changes in the address of workshop, shall be intimated to the Director of Boilers.

8. Application for renewal of Recognition shall be made at least two months before the expiry of the said period.

9. In case the repairer is found indulging in violating the provision of the Act/Regulations knowingly or unknowingly, the firm shall be blacklisted and renewal will not be done in any case.

* * *