Pline sync

- Goal
 - Sync exposure setting as Target phone
 - Sync AE brightness as Target phone
- Side effect
 - Non



- Gray wall with High or Mid color temperature light source
- 24 color checker put in the center
- 1 lux to 1000 lux

CONFIDENTIAL B

1, 3, 5, 7, 10, 15, 20, 30, 40, 50, 60, 70, 80, 90, 100, 150, 200, 250, 300, 350, 400, 450, 500, 600, 700, 800, 900, 1000

How to fine tune

- Brief of all
 - Take images under each luminance and then make a list of exposure setting and Y mean.
 - Tuning AE target at normal light & Low light (NS) to sync brightness
 - Tuning NS sBVRatio to decide which BV start to NS mode
 - Plan exposure setting of each luminance to sync Pline
 - Discuss with customer and verify
 - Pline might be not all the same as target phone due to different sensitivity, Fn, ISO....







Pline sync

- How to fine tune in detail
- Sync AE brightness

MEDIA1

- List target exposure /Y mean
- Analysis Y mean
- Classify into normal light brightness and low light brightness region
- Fine tune AE target to fit normal brightness
- Fine tune NS target to fit
 NS brightness
- Decide which BV start entering to NS
 - Modify NS sBVRatio
- Ex. Check DP info of 100&150 lux JPGs took by tuning phone to get BV info.

AE_TAG_LV	50
AE_TAG_EV	Ŭ.
AE_TAG_REALBV	18
AE_TAG_CUMPBV	18
AE_TAG_AE_SCENE	1
AE_TAG_EV_COM	0
AE_TAG_FLICKER	2
AE_TAG_FLICKER_AUTO	1/
AE_TAG_AEMETER	0
	AE_TAG_EV AE_TAG_REALBV AE_TAG_CUMPBV AE_TAG_AE_SCENE AE_TAG_EV_COM AE_TAG_FLICKER AE_TAG_FLICKER_AUTO

Target phoe		۸7	
Target phoe	A7 2		
Lux			
			Y mean
3	1/15		5.62 15.3
	1/15	800	
5	1/15 1/15	800 800	
10	1/15	800	
		800	
15	1/15		
20	1/15	800	
30	1/15	800	
40	1/15	640	
50	1/15	500	
60	1/15	400	124.37
70	1/15	400	127.29
80	1/15	320	127.74
90	1/15	320	128.74
100	1/15	250	129.46
150	1/15	200	135.46
200	1/15	160	136.97
250	1/20	160	137.52
300	1/24	160	138.66
350	1/24	160	139.06
400	1/30	160	139.16
450	1/30	125	137.7
500	1/30	125	138.15
600	1/30	100	138.3
700	1/40	125	138.8
800	1/40	100	139.71
900	1/40	100	137.51
1000	1/40	80	137.99

Max BV range

NS brightness

NS BV

Normal brightness

Pline sync

- How to fine tune in detail
- Sync exposure setting
 - List exposure
 - Analysis shutter/ISO
 - Classify into exposure/ISO segments
 - Plan Pline segments to fit target phone exposure/ISO segments
- Discuss with customer and verify
 - It might not fit 100% as target phone please make a discuss and then make a decision
 - Re-take images of tuning phone to verify

Target phone	A7		
Fn	2		
Lux	Shutter	ISO	Y mean
1	1/15	800	5.62
3	1/15	800	15.3
5	1/15	800	31.16
7	1/15	800	45.09
10	1/15	800	60.35
15	1/15	800	78.57
20	1/15	800	97.69
30	1/15	800	121.66
40	1/15	640	125.94
50	1/15	500	125.27
60	1/15	400	124.37
70	1/15	400	127.29
80	1/15	320	127.74
90	1/15	320	128.74
100	1/15	250	129.46
150	1/15	200	135.46
200	1/15	160	136.97
250	1/20	160	137.52
300	1/24	160	138.66
350	1/24	160	139.06
400	1/30	160	139.16
450	1/30	125	137.7
500	1/30	125	138.15
600	1/30	100	138.3
700	1/40	125	138.8
800	1/40	100	139.71
900	1/40	100	137.51
1000	1/40	80	137.99

Max BV range

Turning point 3

Turning point 2

Turning point 1



Normal light & Low light Face AE brightness

Goal

 Face AE brightness is close to target phone both on normal and low light condition

Side effect

Non

Scene

- Gray wall with human face (half portrait)
- FD is detected
- 20-150 lux
 20, 30, 40, 50, 60, 70, 80, 90, 100, 150, 500

How to fine tune

- Brief of all
- If face detection region is usually not reliable, increase uLandmarkWeight to use landmark weighted Face brightness.
- Take face images on each lux and list Y mean of full image.
- Fine tune Face target
 - Brighter ambient → uFaceYHighBound
 - Darker ambient → uFaceYLowBound
 - Night scene → u4FaceNSLowBound
- Verify

For details, please reference Face AE tuning.

If FD region is bad or can not detected, please contact with FD feature owner to improved.





Normal light & Low light Face AE brightness

- How to fine tune in detail
 - List Y mean of full image
 - Classify into Normal brightness and Low brightness
 - Fine tune Face target to let Y mean of full image close to target
 - Normal brightness → uFaceYHighBound
 - Low brightness → uFaceYLowBound
 - With NS → u4FaceNSLowBound

For details, please reference Face AE tuning.

e	Target phoe	A7	
	Fn	2	
X	Lux	Y mean	
	20	97.69	
O _V	30	121.66	
Г	40	125.94	
ı	50	125.27	
ı	60	124.37	→ Low
ı	70	127.29	brightness
ı	80	127.74	brightness
L	90	128.74	
	100	129.46	
	150	135	
	500	135	→ Normal
Ī			brightness