

QC-SOP-016 — Internal transfer, rework and physical disposition

Revision D0.2 | DRAFT FOR REVIEW | Revised 2026-10-04

Effective date: not recorded. Approval/signature: not recorded. This draft does not authorize testing, release, production changes or UAT acceptance.

1. Purpose and scope

Move, rework, return or dispose of controlled material only after an authorized disposition and quantity reconciliation.

Implementation: PROPOSED MANUAL PROCEDURE — DIGITAL MOVEMENT LEDGER REQUIRED

2. Responsibilities and review

Responsible specialists: Warehouse; Production; QC Supervisor; QMS

Review: Warehouse; Production; QC Supervisor; QMS

Approval: Authorized QMS / Document Control approver under the approved document policy; not yet established for this draft

3. Before you start

- The disposition identifies material, lot, quantity, permitted destination and restrictions.
- The sending and receiving locations can preserve status.
- The technical owner has approved any rework method and reinspection requirement.

4. Procedure

1. Read the disposition and verify its authority and affected quantity. A report title, printed signature box or proposed checkbox is not sufficient authorization.
2. Create a controlled movement record containing origin, destination, lot, quantity, unit, condition, reason and related QC record identifiers.
3. Before movement, count the segregated units and reconcile partial lots. Preserve rejected or HOLD status on labels and containers.
4. For rework, issue the approved instruction and identify who may perform it. Record the original defect, work performed and new inspection requirement; do not relabel material as accepted on completion of rework alone.
5. The receiver checks identity, quantity and status and records receipt. Document discrepancies before merging material into another location or production order.
6. Return the completed movement evidence to QC and the source record owner. The current system has no dedicated stock-transfer execution or inventory-balance ledger for this procedure.
7. Perform the required reinspection or retest as new linked work, keeping the original failure and disposition history.
8. Close the physical reconciliation after sender and receiver resolve any balance. QMS must approve disposal controls and retention requirements separately.

5. Decisions, errors and stop conditions

- An absent disposition or destination acceptance stops movement.
- Do not interpret a rejected-material report completion as proof that physical transfer or destruction occurred.

6. Records and handoff

- Disposition approval
- Movement and quantity reconciliation
- Rework execution
- Reinspection and destination receipt

Before handoff, reopen the saved record where the application supports it and compare the result with the source. Retain an unresolved outcome as unresolved; do not infer approval from a name, signature image, task completion or test result.

7. Sources and related documents

- Documents/REJECT-REPORTS.md
- Documents/DECISION-ASSUMPTION-REGISTER-026.md

Related work instructions: QC-WI-025

Repository sources are bound to HEAD 435f9f704049dee4916223b24b96866d7fa9af2e. Resolve source IDs, file hashes, external editions and form originals in References (source metadata is inside Authoring_Sources.zip).

8. Required decisions before approval

- DEC-019 — Training, sample custody and movement

Document Control records real reviewer outcomes and actual approval/effectivity only after the controlled process. Completed proposals for these decisions are provided in References/Policy_and_Method_Decision_Book.pdf. Required source evidence and owner adoption remain explicitly recorded there.

10. Detailed operating policy and review checks

These are D0.2 proposed operating controls for adoption. Official company records remain valid physical source records; this revision does not retrospectively change their outcomes. Use the operational record named below to capture execution and exceptions.

DEC-019 — Training, custody and movement

The assessor observes identity checks, correct source selection, a normal task, a deliberate exception, raw-data recording and safe handoff. Record each result and restriction. Reassess following a significant method/equipment change, an observed competence failure or the approved review schedule. Training attendance alone is insufficient.

Decision and exception check: For custody, record sample ID, parent lot, selection time, selector, quantity, condition, container/seal and every transfer with both parties and time. For movement, reconcile opening quantity, received/transferred, tested/destroyed, reworked, scrapped and closing balance in one unit. Discrepancies stop handoff until explained; maintain quarantine identity through transport.

Record: QC-REC-003, QC-REC-010 movement, QC-REC-012 competency; QC-SOP-002/007/016.

11. Official physical record workflow

Use F-7-5-7-8 Rev4. Select the actual Production/Warehouse origin, record date, item description, lot, unit, line quantity and total quantity. Attach the referenced incident/test report and identify the exact reason for rejection, including item code where shown in remarks.

Complete preparation and review in the physical workflow. Keep Checked by Production Team distinct from Reviewed by Quality Controller, and keep both distinct from the approval section for Production Manager, Quality Control Manager and Factory Director. The photographed warehouse report carries a documented Production-signature exception; retain its scope without generalizing it to every rejection.

Record proposed Rework, Transfer to Warehouse or Other disposition, then obtain the real approval before execution. Rework completion needs its own evidence and reinspection; selecting Rework does not show that it happened. Reconcile quantities sent, returned, scrapped and remaining. The digital confirmation is entered only by an authorized actor and linked to the real source.

Completion check: origin, lot, unit, quantities, reason, disposition, approval evidence and movement/reinspection references all agree. Keep the original report with its signatures and dates intact.

Revision record

D0.2, 2026-10-04: expanded execution, exception and handoff controls; incorporated owner-confirmed official physical forms and completed technical decision proposals. Previous D0.1 sources are retained in History/D0.1 within Authoring_Sources.zip. Review and approval remain unrecorded.