- connector terminals 1 and 2 12 [B].
  Compare resistance indicated with that specified.
- Disconnect each injector valve multi-plug in turn.
- Connect ohmmeter between injector terminals 13.
- Compare resistance indicated with that specified.

#### 2.7 Manifold absolute pressure (MAP) sensor

#### Checking

- MAP sensor is incorporated in ECU.
- Sensor operation can only be checked using VAG 1551 diagnostic unit.



2.8 Lambda

sensor

2.9 Overrun cut-

### Checking

 Lambda sensor operation can only be checked using VAG 1551 diagnostic unit.




off

### Checking

 Overrun cut-off can only be checked using VAG 1551 diagnostic unit.

## Self-diagnosis

- Digifant system is equipped with Selfdiagnosis.
- ECU memory may be acessed to read fault codes see Self-diagnosis section.
- Diagnostic connectors are located behind flap in glovebox.



/Autodata

# VOLKSWAGEN

Polo G40 1,3

1991-04

# ECU Multi-plug

25 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1

