

Default bindkeys (schematic)

Esc	F1	F2	F3	F4	F5	F6	F7	F8	F9	F10	F11	F12	Del	Comment				
Unselect tool			Options menu										Delete component					
~ 、	1	2	3	4	5	6	7	8	9 Delete probes Add probe	0	-	= Switch view	← Backspace					
Tab ↔	Q Properties	W Wire	Wide wire	E Descend read	Ascend read	R Rotate	↖ ↗	T Edit text	Y	U Undo	I Instance	O Display settings	Editor	P Pin	[Zoom out	] Zoom in	 \ Enter	
Caps Lock ↑	A	S	D	F Fit-to-screen	G Find marker	H	J	K	L Label	:	; '	"	↵					
Shift ↑	Z	X Check + save Save	C Copy	V	B Block	N Text Note Note shape	M Move	< ,	> .	?	/	Shift ↑						
Ctrl	Win	Alt	Create nets and labels automatically							Alt	Win		Ctrl					

AnalogHub.ie

Default bindkeys (layout)

Esc Unselect tool	F1	F2	F3 Options menu	F4	F5	F6	F7	F8	F9	F10	F11	F12	Del Delete component
~ `	1	2	3	4	5	6	7	8	9	0	- _	= +	← Backspace
Tab ↩↪	Q Properties	W	E Ascend read Descend read	R Rotate	T	Y	U Undo	I	O Place via	P Wire	[Zoom out	] Zoom in	 \
Caps Lock ⬆⬆	A	S Stretch	D	F Fit-to-screen	G	H	J	K Remove rulers Ruler	L	: ;	" '	Enter ↵	
Shift ⬆		Z	X	C Copy	V	B	N	M Move	< ,	> .	? /	Shift ⬆	
Ctrl	Win	Alt								Alt	Win		Ctrl

AnalogHub.ie

[Useful hotkeys Cadence Virtuoso - AnalogHub](#)

<https://github.com/analoghub-ie>

EE3408C Project

- part 3 has parameter