Ex.No.-1.2-Design and Draft the given 2D Sketches in modelling software.

AIM

To sketch the given drawing with dimensions using fusion 360 tool.

REQUIREMENTS

Autodesk fusion 360


Windows 10

16 GB of RAM (integrated graphics recommend 1 GB or more)


2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE


1. Open new file and then select sketch icon.
2. Select the plane for sketching.
3. Use sketching features (line, circle, arc, rectangle, polygon, etc.,) to draw the given sketch




4. Use sketch modifying features (cut, trim, mirror, move, etc.,) to edit the sketch.




5. Use inspect feature to measure the dimensions of sketch.




6. After finishing the sketch use finish sketch option to finalize the sketch.




7. After finishing the sketch switch to drawing mode to plot the sketch in ISO standard.



DESIGN
SOLID
SURFACE
CREATE
DESIGN
GENERATIVE DESIGN
RENDER
ANIMATION
SIMULATION
MANUFACTURE
DRAWING
From Design
From Animation



CREATE DRAWING
Reference
Contents
Full Assembly
Destination
Drawing
Create New
Template
From Scratch
Standard
ISO
Units
mm
Sheet Size
A3 (420mm x 297mm)
OK
Cancel

SKETCHS


R15
R21
50
R21
R20
R16
R15
R32
60
R20
R20
R15
R21
R40
6
R20
R15
R15
R21
20
50
50
60

OUTPUT





RESULT

Thus the given sketch is drawn and drafted using fusion 360 tool.