1.Driven camera on Windows

1. Install OrbbecViewer

Extract the OrbbecViewer.zip compressed package from the attachment folder, which contains OrbbecViewer.exe. Double click to run this program.

2. Run OrbbecViewer

Connect the camera and host using a USB cable, double-click OrbbecViewer.exe, and the following screen will appear after successful operation.



Connect the camera and host using a USB cable, double-click OrbbecViewer.exe.

And the following screen will appear after successful operation.



To view the point cloud, click on it, and the effect is as follows.

