PC Communication

PC Communication

- 1. Experiment Preparation
- 2. Experiment Wiring
- 3. Viewing Serial Port Data

Note: If the serial port cannot be recognized, please install the ch340 driver.

1. Experiment Preparation


- IMU Attitude Sensor
- Type-C Data Cable

2. Experiment Wiring



3. Viewing Serial Port Data

Configure the serial port assistant as shown in the following figure.



The serial port prints unprocessed data. For the specific meaning of the data, please refer to the "**Communication Protocol**" document.