
## 1. Wiring and Testing

PICO	expansion	LED bar
board		
5v		VCC
GND		GND
GPIO22		LED

## Wiring diagram



## 2. Test

1. Open the routine "light\_strip\_14.py" file we provided with Thonny software Then release the comment before the function that needs to be tested and run it

For example: I am testing the breathing light here, just delete the "#" before the breathing light function. If you need to run other functions, you can re-comment the breathing light with "#", and then delete the "#" before other function calls.