



GND: connect gnd	OUT: Single bus digital signal output	+: Connect 3.3V, 5V
Range	Humidity: 20-90%RH	Temperature: 0~50°C
Accuracy	Humidity: ±5%RH	Temperature: ±2℃
Resolution	Humidity: 1%RH	Temperature: 1℃

DHT11 is a temperature and humidity sensor. Its accuracy range, humidity: + -5% RH, temperature: + -2 $^{\circ}$ C. Measuring range, humidity: 20-90% RH, temperature: 0 $^{\circ}$ 50 $^{\circ}$ C.