Key KPIs with Targets:

- **Total Downtime:** Aim to minimize overall downtime.
- **Product Downtime:** Reduce downtime for top delay-causing products.
- **Downtime Factors:** Target main causes like batch changes and machine adjustments.
- Operator Downtime: Lower downtime linked to operator errors through training.
- Current vs Target Production Rate: Measure actual production rate against the 80% efficiency goal.
- Operator Efficiency: Track individual operator productivity and downtime to find improvement areas.
- Average Batch Time: Decrease batch time without sacrificing quality.

Dashboard:

