

EXPERIMENT -1

NAME: YAMUNA V
REG NO: 23MIS0279

BAD DESIGN 1:

DESCRIPTION:

A Door has no “push “ or “Pull” label , making it difficult for users to know how to open it. People often try to pull when they should push ,or push when they should pull.

Source of Photograph:



Place: College, VIT vellore ,sjt

Reasons why the design is bad:

- 1, No clear instructions for users
- 2, Causes confusion and frustration
3. Wastes time while opening the door

Suggested Improvement:


1. Add clear “push “ and “pull” labels.
2. Make labels large and easy to read.

BAD DESIGN 2:

DESCRIPTION:

A water pipe has leakage due to poor sealing at the pipe joint. Water continuously drips the connection, leading to water wastage.

Source of Photograph:



Place: College, VIT vellore ,sjt

Reasons why the design is bad:

1. poor sealing causes water leakage.
2. Wastes water continuously.
3. Can damage nearby walls and floors.

Suggested Improvement:

1. install high quality pipe joints.
2. Inspect and maintain pipes regularly.
3. Test joints after installation.

BAD DESIGN 3:

DESCRIPTION:

The PRP Block in my college has confusing room numbering and limited directional signs. Students and visitors find it difficult to locate classrooms ,laboratories,and faculty rooms.

Source of Photograph:



Place: PRP Block, VIT vellore.

Reasons why the design is bad:

1. Lack of clear directional signboards.
2. similar looking corridors cause confusion.
3. First time visitors often get lost.

Suggested Improvement:

1. Install clear directional signboards.
2. Place a building map at the entrance.
3. Introduce color coded sections for each floor.