
D amplitude scan: linearity diagnostic, not IID repetitions
Open circles: numerical check not met; red crosses: solver failure
f1
f2
f3
zeta1
zeta2
zeta3
Hz
Damping (%)
Disturbance amplitude gain
Direct, lines
Reference IV
Weighted reference IV