

SYNTHETIC TEST DOCUMENT — INSPECTION REPORT

Golden E2E test corpus | Not an actual MRPL document

Inspection identity

Report ID: INSP-FV-201A-07
Inspection date: 2026-08-20
Equipment: FV-201A

Inspection findings

Finding	Observed value	Assessment
Wall corrosion	0.12 mm	Within synthetic acceptance criterion
Valve body	Globe	Matches specification
External condition	Minor coating wear	Maintenance attention recommended
Leak indication	None observed	No leak indicated

Maintenance recommendation

Schedule routine maintenance attention for coating wear during the next planned maintenance window.

Ground-truth note

For golden tests, FV-201A has measured corrosion of exactly 0.12 mm and is marked for routine maintenance attention.