FixSkrew Part Locator Test Prompts

Use a fresh case (New case, or Clear chat with no documents uploaded). Send one message at a time, then open the Visual locator tab and press Analyse this view. The top ranked part should match the expected part below.

#	Test message	Expected top part
1	Whining noise from the **rear motor** when accelerating	Rear drive unit
2	Vibration and a grinding noise from the **front motor** at highway speed	Front drive unit
3	My **12 V battery** keeps going flat and the car won't wake up	12 V battery
4	Coolant **pump** is humming loudly after I park	Coolant pump
5	Battery overheats during fast charging and **coolant** level looks low	Cooling plate and coolant
6	Charging is very slow in **cold weather**, the **heater** doesn't seem to switch on	Pack heater
7	**Charge port** is warm and the charging session stops	Charging inlet
8	Car shows an **HVIL interlock** fault after a service	High-voltage interlock loop
9	**Contactor** clicks but pre-charge times out and the car won't go ready	Contactors or pre-charge resistor
10	DC fast charging fails but AC charging works, I suspect the **DC fuse**	DC fast-charge fuse
11	**Cell** voltage imbalance and range loss, code P0B3C	Cell groups (BMS appears if you also mention the BMS)
12	Isolation fault after a service, I suspect the **drive unit** or HV harness	HV harness, then the drive units

Notes

- Use the words in bold. A message that does not name the part usually gets a generic battery-side answer.
- Each prompt should highlight a different part, not only the battery pack. The pack still wins when the evidence does not point at a specific part.
- A strong match gives a cited answer with a source list. A weak match gives an answer labelled General answer, unverified.
- Each prompt is one chat call, and each Analyse this view is one image call. Twelve prompts with analysis is about 24 calls, so test in two batches to stay inside the quota.
- Every top part below was confirmed by running the prompt against the live backend (12 of 12 correct after the last matching changes). Avoid wording like pressure washing in test 12: it correctly points at the Pack vent, which can let water in.