

Lathe X-90 — Operation & Maintenance Manual

Overview

CNC lathe with 2-axis control plus live tooling. Chuck size: 200 mm. Max turning diameter: 320 mm.

Safety

Never reach into chuck while powered. Use chuck guard at all times.

Tool Post

Corrective maintenance note: tool post alignment should be checked after any collision. Run test bar at 500 RPM.

Maintenance

Grease tailstock every 250 hours. Check belt tension monthly. Current efficiency target: 75%+.

Programming

Use G96 constant surface speed for finishing passes. Recommended insert grade: CNMG 120408.

Emergency Contacts

- 1 Maintenance Lead: ext. 204
- 2 Plant Manager: ext. 101
- 3 Safety Officer: ext. 999