											ES	вмс													
Controller	FORMAT <k,l></k,l>	LIMIT_CYCLE						OVERFLOW- SATURATE MODE						OVERFLOW- WRAPAROUND MODE						STABILITY					
		DFI		DFII		TDFII		DFI		DFII		TDFII		DFI		DFII		TDFII		DFI		DFII		TDFII	
		VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT
ds-01	<2,14>	s	0.23	S	0.29	S	0.33	F	1.04	F	1.06	F	1.19	F	0.93	F	1.2	F	1.23	S	0.16	S	0.13	S	0.14
	<4,12>	s	0.23	S	0.37	S	0.33	S	1.34	S	3.92	S	1.63	S	1.16	S	1.25	S	1.75	S	0.16	S	0.17	S	0.14
	<6,10>	S	0.46	S	0.39	S	0.36	S	1.33	S	1.25	S	3.08	S	2.86	S	2.53	S	1.39	S	0.17	S	0.13	S	0.13
ds-02	<6,10>	S	0.23	S	0.3	S	0.35	F	1.87	F	1.85	F	2.29	F	4.19	F	2.34	F	2.03	S	0.17	S	0.14	S	0.14
	<8,8>	S	0.23	S	0.3	S	0.33	S	8.45	S	6.46	S	3.21	S	2.43	S	6.9	S	2.58	S	0.17	S	0.14	S	0.14
	<10,6>	s	0.27	S	0.31	S	0.29	S	2.29	S	2.09	S	3.01	S	2.92	S	8.25	S	2.63	S	0.13	S	0.14	S	0.14
ds-03	<7.9>	s	0.31	S	0.29	S	0.3	F	2.05	F	2.16	F	2.76	F	2.56	F	3.98	F	2.1	S	0.14	S	0.14	S	0.14
	<9,7>	s	0.27	S	0.3	S	0.29	S	2.68	S	7.33	S	3.79	S	3.24	S	10.94	S	2.81	S	0.17	S	0.14	S	0.14
	<11,5>	s	0.26	S	0.3	S	0.31	S	2.76	S	3.87	S	3	S	3.08	S	7.6	S	2.94	S	0.16	S	0.14	S	0.14
ds-04	<8,8>	F	4.75	F	8.54	F	5.84	F	3.57	F	3.21	F	6.28	F	4.62	F	3.94	F	4.2	F	0.32	F	0.33	F	0.32
	<10,6>	F	6.56	F	9.95	F	5.48	S	32.91	S	34.9	S	49.42	S	49.51	S	37.46	S	47.23	F	0.32	F	0.33	F	0.32
	<11,5>	F	5.94	F	12.19	F	6.05	S	27.17	S	26.62	S	33.14	S	43.26	S	34.37	S	36.29	F	0.33	F	0.33	F	0.33
ds-05	<10,6>	F	6.95	F	14.56	F	7.64	F	3.6	F	4.43	F	3.8	F	5.35	F	9.87	F	4.51	F	0.32	F	0.33	F	0.33
	<12,4>	F	6.23	F	17.19	F	3.69	F	3.22	F	4.8	F	4.79	F	4.54	F	4.95	F	4.64	F	0.32	F	0.33	F	0.33
	<13,3>	F	4	F	7.14	F	5.98	F	3.13	F	4.25	F	3.42	F	3.88	F	10.16	F	4.72	F	0.32	F	0.33	F	0.33
ds-06	<4,12>	F	6.25	F	9.1	F	6.83	F	25.94	F	32.41	F	26.98	F	40.92	F	20.52	F	37.76	F	0.31	F	0.32	F	0.31
	<8,8>	F	3.14	F	8.2	F	5.04	S	6.7	S	26.12	S	9.07	S	7.96	S	32.39	S	7.15	F	0.37	F	0.32	F	0.32
	<10,6>	F	4.83	F	6.23	F	4.31	S	5.22	S	11.89	S	5.11	S	6.18	S	13.97	S	4.43	F	0.41	F	0.32	F	0.32
ds-07	<4,12>	S	8.55	F	10.12	S	19.02	S	13.3	S	35.11	S	32.64	S	15.99	S	25.04	S	36.04	F	0.38	F	0.32	F	0.31
	<8,8>	s	4.92	F	7.06	S	11.3	S	6.21	S	17.76	S	6.92	S	6.91	S	18.26	S	6.41	F	0.44	F	0.39	F	0.31
	<10,6>	S	3.5	F	6.5	S	9.5	S	3.39	S	5.97	S	3.29	S	3.44	S	5.4	S	3.7	F	0.44	F	0.35	F	0.32
ds-08	<3,13>	S	0.27	S	0.31	S	0.29	S	17.98	F	3.37	S	22.82	S	22.89	S	6.97	S	23.19	S	0.19	S	0.19	S	0.14
	<4,12>	S	0.23	S	0.31	S	0.29	S	7.74	F	7.08	S	8.69	S	20.95	S	18.82	S	9.15	S	0.18	S	0.19	S	0.14
	<5,11>	S	0.34	S	0.3	S	0.29	S	12.08	F	2.3	S	11.61	S	4.25	S	7.01	S	14.38	S	0.19	S	0.15	S	0.21
ds-09	<4,12>	S	9.45	F	9.98	S	19.03	S	13.45	S	30.69	S	33.14	S	17.67	S	24.61	S	33.74	F	0.55	F	0.4	F	0.37
	<8,8>	S	4.7	F	7.04	S	11.36	S	6.24	S	14.88	S	5.79	S	7.8	S	17.27	S	6.21	F	0.41	F	0.32	F	0.32
	<10,6>	S	3.34	F	6.54	s	9.77	S	3.55	S	4.83	S	2.81	S	3.14	s	6.26	s	3.26	F	0.37	F	0.34	F	0.32