											CBM	С													
Controller	FORMAT <k,l></k,l>	LIMIT_CYCLE						OVERFLOW- SATURATE MODE						OVERFLOW- WRAPAROUND MODE						STABILITY					
		DFI		DFII		TDFII		DFI		DFII		TDFII		DFI		DFII		TDFII		DFI		DFII		TDFII	
		VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT	VR	VT
ds-01	<2,14>	S	8.68	S	5.73	S	22.16	F	0.12	F	0.14	F	0.11	F	0.13	F	0.14	F	0.11	S	0.01	S	0.01	S	0.01
	<4,12>	S	6.64	S	5.48	S	22.45	S	0.14	S	0.14	S	0.11	S	0.14	S	0.11	S	0.12	S	0.01	S	0.01	S	0.01
	<6,10>	S	4.44	S	2.5	S	20.73	S	0.15	S	0.13	S	0.11	S	0.11	S	0.11	S	0.11	S	0.01	S	0.01	S	0.01
ds-02	<6,10>	S	13.93	S	7.62	S	60.8	F	0.11	F	0.12	F	0.11	F	0.12	F	0.12	F	0.11	S	0.01	S	0.01	S	0.01
	<8,8>	S	3.12	S	2.54	S	31.02	S	0.16	S	0.18	S	0.13	S	0.16	S	0.14	S	0.14	S	0.01	S	0.01	S	0.01
	<10,6>	S	1.64	S	1.3	S	9.4	S	0.15	S	0.15	S	0.12	S	0.2	S	0.13	S	0.12	S	0.01	S	0.01	S	0.01
ds-03	<7.9>	S	6.26	S	5.27	S	45.97	F	0.12	F	0.13	F	0.14	F	0.15	F	0.12	F	0.12	S	0.01	S	0.01	S	0.01
	<9,7>	S	2.71	S	1.88	S	17.46	S	0.22	S	0.18	S	0.13	S	0.16	S	0.14	S	0.14	S	0.01	S	0.01	S	0.01
	<11,5>	S	1.28	S	1.19	S	4.88	S	0.16	S	0.17	S	0.13	S	0.14	S	0.12	S	0.12	S	0.01	S	0.01	S	0.01
ds-04	<8,8>	F	1.59	F	1.62	F	1.91	F	0.26	F	0.18	F	0.2	F	0.2	F	0.18	F	0.14	F	0.08	F	0.08	F	0.08
	<10,6>	F	1.8	F	1.82	F	2	S	6.78	S	1.45	S	2.84	S	7.7	S	1.98	S	3.5	F	0.08	F	0.08	F	0.08
	<11,5>	F	1.48	F	1.88	F	1.82	S	2.06	S	1.31	S	1.7	S	2.1	S	1.06	S	4.51	F	0.08	F	0.08	F	0.08
ds-05	<10,6>	F	6.49	F	1.55	F	1.99	F	0.25	F	0.21	F	0.21	F	0.21	F	0.19	F	0.21	F	0.1	F	0.1	F	0.1
	<12,4>	F	1.43	F	1.7	F	1.85	F	0.18	F	0.21	F	0.22	F	0.2	F	0.18	F	0.2	F	0.1	F	0.1	F	0.11
	<13,3>	F	1.67	F	1.82	F	2.32	F	0.26	F	0.19	F	0.23	F	0.23	F	0.19	F	0.2	F	0.1	F	0.1	F	0.1
ds-06	<4,12>	F	1.1	F	1.4	F	1.77	F	1.32	F	0.44	F	0.84	F	1.39	F	1.14	F	1.18	F	0.03	F	0.03	F	0.03
	<8,8>	F	1.23	F	1.38	F	1.41	S	1.03	S	0.69	S	0.62	S	1.03	S	0.65	S	0.72	F	0.03	F	0.03	F	0.03
	<10,6>	F	1.2	F	1.44	F	1.3	S	0.7	S	0.61	S	0.58	S	0.71	S	0.88	S	0.53	F	0.03	F	0.03	F	0.03
ds-07	<4,12>	S	16.91	F	5.04	S	176.69	S	0.86	S	0.64	S	0.71	S	0.83	S	0.74	S	0.5	F	0.03	F	0.03	F	0.03
	<8,8>	S	4.54	F	9.02	S	32.23	S	1.01	S	0.54	S	0.58	S	0.91	S	0.48	S	0.53	F	0.03	F	0.03	F	0.03
	<10,6>	S	2.9	F	5.71	S	15.31	S	0.71	S	0.49	S	0.62	S	0.77	S	0.42	S	0.57	F	0.03	F	0.03	F	0.03
ds-08	<3,13>	S	9.45	S	78.57	S	409	S	0.33	F	0.16	S	0.29	S	0.22	S	0.23	S	0.32	S	0.01	S	0.01	S	0.01
	<4,12>	S	7.36	S	43.55	S	204.55	S	0.33	F	0.16	S	0.23	S	0.27	S	0.21	S	0.22	S	0.01	S	0.01	S	0.01
	<5,11>	S	3.2	S	19.93	S	33.21	S	0.19	F	0.13	S	0.16	S	0.2	S	0.16	S	0.17	S	0.01	S	0.01	S	0.01
ds-09	<4,12>	S	12.7	F	5.96	S	220.49	S	0.86	S	0.64	S	0.7	S	0.73	S	0.74	S	0.5	F	0.03	F	0.03	F	0.03
	<8,8>	S	4.55	F	8.39	S	30.75	S	1	S	0.54	S	0.59	S	0.84	S	0.48	S	0.53	F	0.03	F	0.03	F	0.03
	<10,6>	S	3.06	F	9.33	S	15.63	S	0.72	S	0.49	S	0.63	S	0.63	S	0.42	S	0.57	F	0.03	F	0.03	F	0.03