714-17 Date Page 10T Sels: Assignment 1 Aim: Write and wriplement a program to FRASH or SCROLL 3 LADS continuousty continuousty Apparatus: 3 LEDs, Ardvino uno board, connecting wires. 1. Set permode to expert to led 1=13. led 2=12, led 3-8 in netup () function. 2. First turn on all leds with digital with digital 3. In the next 3 consolutive steps torn of each LED with digital wrete to fow with a delay of 2500ms between each digital write Ofter this all 3 Ups sounds 4. In the next 2 consecutives steps turn on LBD28 led 3 to HIGH with delay of 500ms