
Title: Temperature Senson.

Aim: To record the temperature using the sensor.

Hardware Required: Auduino Board, Wire, Temperature Senson.

Circuit Diagram:



```
Cede:
int outputpin = 0;
void setup()

! Serial.begin (9600);

void loop()
! int nawvoltage = an alog Read Contputpin);
float millivolts = (nawvoltage 11024.0) * 5000;

float celsius = millivolts 110;

Serial. print (celsius);

Serial. print ("Degree Celsius,");
```

Serial point ("Degree Farenheit"); Serial point ((celsius *9) 15 +32); delay (1000);

Observation / Dusput:

3

We can see the temperature of the surroundings in celsius scale and formerheit scale.

83

1

-1

. 3

Propertion

i agent

alleria ...

Salda Singa

Sup I's to