

	reduced to raise the speed by 50% if the developed torque is constant ? Neglect saturation and armature reaction.		
C)	Explain Field flux and armature resistance control methods for speed control of dc shunt motor	2	6
Q. 5	Solve Any Two of the following. (This is just a sample instruction)		12
A)	Explain full step operation of variable reluctance stepper motor with neat diagram	4	6
B)	Explain construction and working of brushless dc motor.	2	6
C)	Explain concept of energy and coenergy for linear magnetic field system and derive relevant expressions.	2	6
	*** End ***		

The grid and the borders of the table will be hidden before final printing.