Rapid Restoration of Unit No. 8 Generator Step-up Transformer at Nakoso Power Station

The stable supply of electric power requires a minimum reserve rate of 3%. However, ever since the Great East Japan Earthquake in 2011, the margin between the supply and demand of electricity in Japan has been tight. When demand for electric power increases due to extremely hot or cold weather and the risk grows of not securing the 3% reserve rate, the authorities issue a power crunch warning or alert. It was in this context that on September 16, 2021, a failure due to aging forced the emergency stop of the unit No. 8 generator step-up transformer (built in 1981) at the Nakoso Power Station of Jōban Joint Power Co., Ltd. This shut down the supply of 600,000 kW of electric power, which is equivalent to about 1% of the total demand peak in the Tokyo area. Hitachi, Ltd. received a request from the customer for the rapid restoration of the power station to help stabilize the power supply in Japan. In a project that would normally take more than a year to deliver from receiving the order to transmitting power, all stakeholders came together as a team to complete the work in about 9 months.

Hikaru Fujita Masaru Kashiwakura Akihiro Kawagoe Hisaki Hamamoto Tetsuo Niitsuma Yuzuru Mitani

1. Introduction

The proportion of Japan's annual power generation capacity taken up by thermal power generation has decreased steadily since the oil crisis in the 1970s. But since the Great East Japan Earthquake in 2011, the proportion increased as thermal power generation replaced nuclear power generation. Then, the proportion of thermal power started to decrease again as the use of renewable energy expanded and some nuclear power stations were restarted; even so, it still makes up about 70% (about 700 billion kWh) of the power supply in Japan.

Of this 70%, the Nakoso Power Station of Joban Joint

Power Co., Ltd., a complex containing three power generators (unit No. 7 generator: 250,000 kW, unit No. 8 generator: 600,000 kW, and unit No. 9 generator: 600,000 kW) provides an amount of power equivalent to about 1% of Japan's thermal power generation (7 to 10 billion kWh annually) to the Tohoku and Tokyo areas. However, on September 16, 2021, a failure due to aging forced an emergency stop of the unit No. 8 generator step-up transformer (GSUT) at Nakoso Power Station. This shut down the supply of 600,000 kW of electric power, which is equivalent to about 1% of the total demand peak in the Tokyo area. In response, Hitachi was requested to conduct rapid restoration work to restart the power generation and help secure the reserve rate of 3%.

2. Overview of Restoration


Figure 1 shows the main circuit configuration around the unit No. 8 GSUT of the Nakoso Power Station that was subject to this restoration project.

After receiving notification about the failure of this transformer, Hitachi quickly dispatched inspectors to the site to investigate the cause of the failure and start considering methods for rapid restoration. Hitachi considered the restoration methods of onsite repair, offsite repair, replacement with a spare from another power plant, or manufacture of a new transformer. Hitachi submitted a report to the customer that detailed the work schedule and various conditions for all of these restoration methods, as well as the results of the cause of failure investigation. After discussing these results together, the customer selected the rapid restoration proposal based on replacing the transformer with one that would be newly manufactured. Hitachi conducted an additional investigation into the cause of failure and considered countermeasures to prevent the same incident from occurring with the new transformer.

Two proposals were considered for where to manufacture the new transformer; at the Hitachi Works Kokubu Factory (Kokubu Factory) or at the Chongqing Factory of

Figure 1 — Schematic Diagram of Nakoso Power Station


In this project, Hitachi worked toward the rapid restoration of the unit No. 8 GSUT.



Hitachi Energy (China) Ltd. (Chongqing Factory). In this project, since Hitachi received consent from the customer to re-examine some of the existing interfacing parts, the Kokubu Factory was selected because it owns the existing

Figure 2 — Overview of Restoration Process Results for Unit No. 8 GSUT

In addition to investigating the causes of the failure immediately after the failure occurred, Hitachi considered various rapid restoration methods and completed the project in about 9 months; normally, the process from receiving the order to transmitting power would take more than a year to deliver.



design. Although the Chongqing Factory was not selected due to transportation times and conditions, the high level of its product manufacturing capacity was confirmed, with almost no difference from the Kokubu Factory, even when considering the new design and the manufacturing period for all the new parts.

Hitachi shortened the process while sharing and consulting with the customer about the risks and opportunities inherent in rapid restoration across the entire project, including manufacturing, transportation, and construction work. This enabled Hitachi to complete the project from receiving the restoration instructions to transmitting the power in a very short delivery time of about 9 months (see Figure 2).

This article describes how Hitachi was able to cope with such a short delivery time while ensuring quality and avoiding accidents.

3. Coping with the Short Delivery Time

This section describes the actions Hitachi took to achieve the short delivery time.

3.1

Project Setup

Immediately after receiving the restoration instructions, Hitachi appointed its internal project members (from the business unit and design, procurement, manufacturing, quality assurance, transportation, and construction departments) and set up regular meetings (within Hitachi: every Tuesday, between the customer and Hitachi: every Wednesday). This created a system that could confirm the progress of work in a timely manner. Hitachi also held ad hoc meetings if any urgent matters were discovered to ensure actions could be taken without delay to avoid risks (process delay or malfunctions) or to make the most of opportunities (shortening the process).

3. 2

Design, Procurement, and Manufacturing Measures

(1) Repeated existing design

Repeating the same design as the existing plant enabled the design time to be shortened compared to completely new manufacturing.

Figure 3 — Overview of Transformer Manufacturing Flow

The process for winding, core stacking, core assembly, final assembly, factory testing, and readying for delivery was shortened via measures such as overtime and day and night work shifts.





Figure 4 — Transportation Route from Onahama Port to Temporary Staying Area to Nakoso Power Station

The overall process from factory shipment to arrival on site was performed in the following order: May 19 (Thursday), night-time transport on public road (Hitachi Works Kokubu Factory to Hitachi Port); May 20 (Friday) 6:00 to 9:30, ship loading (Hitachi Port); 9:30 to 12:30, sea transport (Hitachi Port to Onahama Port); 12:30 to 17:30, unloading from ship (Onahama Port); May 21 (Saturday) 3:00 to 6:00, transport on public road (Onahama Port to temporary staying area); 6:00 to 10:00, waiting (temporary staying area); 10:00 to 12:00 transport on public road (temporary staying area to Nakoso Power Station).



(2) Increased personnel in initial stage of design

Hitachi requested the support of partner companies to increase the speed of creating design plans, arranging materials, and issuing manufacturing instructions.

(3) Delivery times backed up through dual design of parts used

While implementing Plan A, which used all new parts, Hitachi also considered Plan B in parallel, which refurbished and re-used parts that had long delivery times (such as oil level gauges, low-voltage bushings, and resistance thermometers). This hedged the risk if there were any delays in Plan A.

- (4) Identified the shortest supply routes
- (a) Core materials and cutting process (supplier selection) Initially, Hitachi expected to use suppliers within Japan, but due to uncertainty in the status of arranging processing equipment, this was switched to an overseas supplier to mitigate the risk of late delivery.
- (b) Transportation method for on-load tap changer (LTC), a part procured from overseas

Initially, Hitachi expected to use sea transport, but this was changed to air transport to meet the shortened manufacturing schedule at the site, thus avoiding any interruption of the manufacturing process.

(5) Adjusted the manufacturing process

Various process-shortening methods were considered, according to factors such as onsite loading and material receiving status, and the factory shipment date was moved forward from the initially expected date in the middle of

June to May 19, shortening the delivery by about a month (see Figure 3).

3.3

Adjustment of Transportation Process

3.3.1 Transportation Overview


The transportation of the transformer in this project was performed overland from the Kokubu Factory to Hitachi Port, by sea from Hitachi Port to Onahama Port, and then overland from Onahama Port to Nakoso Power Station (see Figure 4).

3. 3. 2 Mitigation Measures and Adjustments with Stakeholders

Even after removing the exterior parts for transportation, the weight of the transformer in this project was 290 t and the stacked height on the vehicle was more than 9 m, making it extremely large equipment. This meant that mitigation measures were required along the transportation route to protect objects buried underground, avoid overhead obstacles, and reinforce bridges. Because there is no quay wall for unloading from a ship at Nakoso Power Station, mitigation measures were required across a wide range, not only on the public road from the Kokubu Factory to Hitachi Port, but also on the public road from Onahama Port to Nakoso Power Station (see Figure 5).

Furthermore, as the factory shipment date was pushed forward, the mitigation process was shortened, necessitating many negotiations with stakeholders related to the roads,

Figure 5 — Photographs of Transportation Route from Onahama Port to Temporary Staying Area to Nakoso Power Station The areas shown in the ovals were the subjects of countermeasures.



vehicles, ports, shipping lanes, ships, heavy machinery, and other areas used for transportation. Usually, the route from the Kokubu Factory to Hitachi Port can only be used at night on Friday. Hitachi needed to negotiate with local citizens, local government, and the police to obtain special permission to travel the route at night on Thursday. Hitachi arranged the schedule so that the ship loading, sea transportation, and ship unloading, which would normally take three days, could be completed on the same day. This avoided work on Sunday, which is prohibited in principle under local restrictions, for unloading the ship at Onahama Port and the transportation on the public road from Onahama Port to Nakoso Power Station. These actions shortened the time from factory shipment to arrival at the site from the normal five days to three days, which was an unprecedentedly short transportation time.

3. 3. 3 Main Stakeholders for Large Equipment Transportation

(1) Kokubu Factory to Hitachi Port

The main stakeholders were the road administrators, overland transportation company, and transportation route countermeasure vendor.

(2) Hitachi Port to Onahama Port

The main stakeholders were the port administrators, ship loading vendor, sea transportation company, and ship unloading vendor.

(3) Onahama Port to Nakoso Power Station

The main stakeholders were the road administrators, overland transportation company, and transportation route countermeasure vendor.

3. 4

Adjustment of Construction Process

3. 4. 1 Adjustment of Work Procedures and Personnel Assignment


Hitachi held repeated discussions with the customer to shorten onsite processes in any way possible, even if only by one day. The process was shortened as much as possible through measures such as improving workability by dismantling the wall of the existing transformer building, and a wrapping process to secure empty space within the power station.

In the installation area, the cable pocket was replaced and the cooler was assembled before the main unit was placed on the base. In parallel, the exterior parts were installed on the main unit in the empty space (assembly area) within the power station, and then the main unit was transported within the site to the installation area, enabling a smooth transition to the next process (see **Figure 6**).

Furthermore, an onsite system was constructed for work on holidays and in day and night shifts by borrowing personnel from other projects and increasing the number of workers from partner vendors. Other actions included reassigning various workers to meet the shipment date that was pushed forward and coordinating with the customer's

Figure 6 — Photographs of Onsite Assembly and Installation Work

Hitachi devised the shortest possible process by improving workability (dismantling the wall of the existing transformer building), performing work before placing the main unit on base (cable pocket replacement, cooler assembly), and performing a wrapping process using empty space (exterior part installation).



work schedule. This enabled the entire work process from equipment arrival to power transmission to be completed with almost no interruptions.

3. 4. 2 Process Adjustment for System Testing and Advance Arrangements

Normally, system testing is often performed together after finishing the equipment standalone testing. However, in this project, the transformer standalone testing that could be performed on the same day, such as LTC remote operation testing, confirmation of remote display of alarm failures, and current transformer (CT) polarity testing, were performed successively.

The cables used for system testing were laid out in advance between each testing location for a smooth transition to the testing process (see Figure 7).

Initially, there was not a single free day planned after the arrival of the equipment, but by continuing to explore every opportunity to shorten the process, the power transmission process that was scheduled for June 29 could be pushed forward by two days to June 27 due to system testing.

3. 4. 3 Main Stakeholders for Onsite Work

(1) Hitachi side

The main stakeholders were the construction workers, on base vendor, transportation route countermeasure vendor (protection of buried objects within site), transformer installation supervisors, transformer installation test inspectors, and system testing inspectors.

(2) Customer side

The main stakeholders were those involved in the advance work (such as existing transformer removal), cable connection, isolated phase bus (IPB) connection, fire hazard inspection, and the power supply department of the power company (arranged for the date of power transmission).

4. Quality Assurance

4. 1

Countermeasure for Potential Malfunctions

Although the existing design was repeated to achieve the shortest possible delivery time, there were some areas of




Figure 7 — Diagram of Cable Layout for System Testing at Site

A communication line (2 cores), standard line (2 cores), and matching phase detection line (1 core) were laid out. The results of an advance site investigation showed the need to lay out new cables for testing in sectors with no existing spare cores.

the 40-year-old design that could not be duplicated. The countermeasures for such areas were reviewed closely by experts as Hitachi made every effort to assure the quality of the new transformer.

4.1.1 Discontinued Parts

(1) Resistance thermometer

The manufacturer had discontinued the manufacture of the existing part, but a different manufacturer was found to produce an alternative (same specifications as the existing part).

(2) High-voltage bushing

The manufacturer had discontinued the manufacture of the existing part, but a different manufacturer was found to produce an alternative. Since the dimensions varied greatly from the existing part, areas such as the interfacing parts and the lead wire were re-examined.

(3) Steel material of main unit tank

The steel marine (SM) material of the existing unit is no longer used, so the current steel structure (SS) material was studied instead.

4. 1. 2 Differences between Initial Delivery and Present Time

(1) Main unit tank material transportation

A transportation compliance review showed that transportation with the same dimensions as the existing unit would not be possible. This resulted in a plate-mounted split structure for the main unit tank.

(2) Review of internal standards

To prevent the overheating of bolts and other parts by the current circulating through locations such as the cable pocket, a conductor for current energization was added to the flange and the welding structure was changed.

4. 1. 3 Matching Interfaces with Existing Cable Heads

Since it was necessary to match the interfaces with the existing cable heads, the dimensions at the site were measured and the structure was changed to one with plenty of allowance for adjustments, such as changing the bolt hole diameters and increasing the number of part divisions.

4. 2


Proposals for Future Preventive Maintenance

The results of the investigation into the cause of the failure of the unit No. 8 GSUT showed that a short circuit occurred between taps. This was caused by overheating and damage of the contacts on the LTC main unit tank side, due to aging. About 40 years had elapsed since this transformer had started operations and the number of LTC switches was about 120,000, which is approximately one quarter of the number of switches generally expected. From these facts, it was deduced that the failure was a phenomenon more likely to occur under the conditions of both "significant aging" and a "low LTC switching frequency." (When surface roughness and level differences between specific contacts progress due to use in a limited tap range and the terminal position remains fixed, overheating occurs more easily due to deterioration of contact energization, carbon adhesion, and other factors.)

As preventive maintenance for the future, in addition to lifting inspections of the changeover switches on the regular maintenance menu, Hitachi added contactor inspections for the LTC segment (tap selection device, polarity switch) on the tank side of the transformer main unit in significantly aged equipment to the maintenance menu.

Figure 8 - Diagram of Induced Voltage Countermeasures

Measures were taken to reduce the induced current when disconnecting and connecting the lead wire between the transformer and cable heads, which reduced the risk of accidental electric shocks and allowed work to proceed.



5. Prevention of Accidental Electric Shocks

During the work disconnecting the existing transformer from the cable heads, induced current from the adjacent operating unit No. 9 was observed. As a result, Hitachi considered countermeasures against electric shocks (see Figure 8).

Measures to reduce the induced current were taken by constructing a detour circuit when disconnecting the lead wire between the existing transformer and the cable heads. The results of subsequent verification also confirmed the effect of reducing the induced current by limiting the output of unit No. 9. Therefore, when connecting the lead wire between the new transformer and the cable heads, in addition to constructing the detour circuit, Hitachi asked the customer to limit the output of unit No. 9, which further reduced the induced current and made the work safe.

6. Conclusions

This project to help solve the social problem of a power supply crunch was an invaluable experience for Hitachi, as it looked beyond conventional frameworks to take the best actions it could, while sharing with the customer information about the risks and opportunities of shortening processes. Hitachi made a significant contribution to power supply stabilization in Japan by rapidly restoring the unit No. 8 GSUT.

Acknowledgments

In the work on the rapid restoration of the unit No. 8 GSUT at the Nakoso Power Station of Jōban Joint Power Co., Ltd., Hitachi received the support of Jōban Joint Power Co., Ltd. and many other stakeholders. The authors would like to express their deepest gratitude to everyone involved in the project.

References

- Agency for Natural Resources and Energy (ANRE), Ministry of Economy, Trade and Industry (METI), "Measures for Electricity Supply and Demand for FY2021 Winter" (Oct. 2021) in Japanese, https://www.meti.go.jp/press/2021/10/2 0211027003/20211027003-1.pdf
- ANRE, METI, "Outlook and Measures for Electricity Supply and Demand for FY2022" (Jan. 2022) in Japanese, https:// www.meti.go.jp/shingikai/enecho/denryoku_gas/ denryoku_gas/pdf/044_04_00.pdf
- Japan Atomic Energy Relations Organization (JAERO), "Nuclear and Energy Drawings [1-2-07] Change in Electricity Generated and Received by Source" in Japanese, https:// www.ene100.jp/zumen/1-2-7
- Jöban Joint Power Co., Ltd., "Electricity Sales and Fuel Consumption" in Japanese, http://www. joban-power.co.jp/category/nakoso_power_plant/ electricity_sales_and_fuel_consumption/

Authors



Hikaru Fujita

T&D Engineering Department, Transmission System Division, Transmission & Distribution Systems Division, Power Grids Business Unit, Hitachi, Ltd. *Current work and research:* Engineering of substation systems for industry.



Masaru Kashiwakura

Transformer Department, T&D Engineering and Production Division, Transmission & Distribution Systems Division, Power Grids Business Unit, Hitachi, Ltd. *Current work and research:* Engineering of maintenance work for large-capacity transformers. *Society memberships:* The Institute of Electrical Engineers of Japan (IEEJ).



Akihiro Kawagoe

Value Integration Center, Energy Business Division, Hitachi, Ltd. *Current work and research:* Procurement of goods for T&D equipment production.



Hisaki Hamamoto

Transformer Department, T&D Engineering and Production Division, Transmission & Distribution Systems Division, Power Grids Business Unit, Hitachi, Ltd. *Current work and research*: Production control of transformers.



Tetsuo Niitsuma

Transmission and Distribution QA Department, Quality Assurance Division of Power Grids Business Unit, Power Grids Business Unit, Hitachi, Ltd. *Current* work and research: Quality assurance of transformers.



Yuzuru Mitani

Business Administration & Engineering Department, T&D Engineering and Production Division, Transmission & Distribution Systems Division, Power Grids Business Unit, Hitachi, Ltd. *Current work and research*: Engineering of transportation and site installation.