CE258 -MPCO 20DCE019

PRACTICAL - 32

<u>AIM:</u> Write a program which sets the parity bit.

CODE:

org 100h

MOV BL, 50H

MOV BH, 50H

XOR BH, BL

NOT BH

ret

OUTPUT:



CONCLUSION: In this practical we can understand how to set value of parity flag.

DEPSTAR-CE Page: 1