

FSR NO. 0500064283

FIELD SERVICE REPORT

NO CHARGE CHARGE	ASC WARRANTY OTHERS
Customer: Tao Yuan Express	Time Arrived: 3.50 pm Date Attended: -24-25
Address: NAIA TI	Time Started: 3 . 50 pm Time Ended: 4 . 00 pm
Contact Person :	
Unit / Description :	INCIDENT No.: APS - 20250124 - 203967
Nature of Call/Problem:	Units/Materials Complete Details :
LVV tao Yuan Express NAIATI: VED	
No Power	
Actions Taken:	
Resocket	
Configured Blos enabled Com 3	
dividence of the control	
Tested and Observed	
Status: OK	
	1 A
Goneida	LAUSIT HOVER
Patrick Garcia SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name
Authorized Service Provider of:	APSOFT.