

FIELD SERVICE REPORT

FSR NO. 020088903

SOFTWARE HARDWARE	OTHERS	****	
Customer MDC TGION	Time Arrived	Date Attended:	20-26
Address: Las piñas Talon	Time Started:	Time Ended:	20-23
Contact Person :	7 10TM	0.0	JUHN
Unit / Description :	INCIDENT No.:	5 - 20250120 - 2	20236
		5 - 2020 20 - 2	-03389
Nature of Call/Problem:	Units/Materials Compl	ete Details :	
TOS #1 and tos#2 1 suki card reader			-
was unable toread	-		
Actions Taken:	-		
checked cable .	-		
Configured main server to copy 1-card	-		1 1 1 1 1 1 1
read Program		T I I I I I I I I I I I I I I I I I I I	100
to the discount			
tested and observed			
Status: Olc		Van	
	-		
0.0572			
Oction Corosa / maday /h.			
SE's Signature Over Printed Name	End User / Officer's	Signature Over Printed Na	ime