

FSR NO. 050 0060884

FIELD SERVICE REPORT

NO CHARGE CHARGE	ASC WARRANTY OTHERS
Customer: GB Wilocks	Time Arrived: 9:50am Date Attended: 1-22-25
Address: Manual turned	Time Started: 0.000mm Time Ended: 5:08 Pm
Contact Person :	
Unit / Description :	INCIDENT No.: 6 TSM -32489
Nature of Call/Problem:	Units/Materials Complete Details :
setup of MPC office Printer	
Biometrics and Printer	
Actions Taken:	
installed MPC TARRED.	
installed Biometrics	
installed Office Printer	
installed Teltonika and Fortinet	
when placed inside cabinet the signal is	
Weak temporary moved Fortinet below	
Pos	
testel and Observed	
Status: OK	
	Dott.
Soters	7 Souland 1 1 2
SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name

Authorized Service Provider of:



and

APSOFT