

## **FIELD SERVICE REPORT**

FSR NO. 020088909

| SOFTWARE HARDWARE  | OTHERS   |
|--|--|
| Customer: MDC  | Time Arrived: %: 10 gas Date Attended: 1-22-25   |
| Address: Ahiban Bacov  | Time Started: G. 10 Pm. Time Ended: G. 18 Pm.    |
| Contact Person :   | 0.10111  |
| Unit / Description :   | INCIDENT No.: PLS - 20250 172 - 203700           |
|  |  |
|  |  |
| E CONTRACTOR OF THE CONTRACTOR |  |
| Nature of Call/Problem:  | Units/Materials Complete Details :               |
| POS 1 Suki card Reader was unable  |  |
| to read  |  |
|  |  |
|  |  |
| Actions Taken:   |  |
| Upon arriving Suki cardiowas said to   | be   |
| tunctioning  |  |
| pos was closed   |  |
|  |  |
| Status: ok   |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  | M  |
| GENTAN   | TO LITCHIE P. GALVELO                            |
| SE's Signature Over Printed Name   | End User / Officer's Signature Over Printed Name |