

FIELD SERVICE REPORT

FSR NO. 020088933

End User / Officer's Signature Over Printed Name

SOFTWARE HARDWARE	OTHERS .		
Customer: MDC	Time Arrived: 055	Date Attended:	1-26-25
Address: South Park Munt City		Time Ended:	11:20gm
Contact Person :			
Unit / Description :	INCIDENT No.: PLS-20250176-20497		
Nature of Call/Problem:	Units/Materials Complete Details :		
Ecr parmaya were not connected on			
tos #4			
Actions Taken:			
Checked Craddle			
Plugged in USB cable to craddle			
paired			
Tested and Observed	The Manual State of		
Statu: OK			
Patrick Garcia	/BN	RUXAS . 1-76-75	

SE's Signature Over Printed Name