

FIELD SERVICE REPORT

FSR NO. 020083238

SOFTWARE HARDWARE	OTHERS			1.00
Customer: MOC	Time Arrived: 3, 224	gm	Date Attended:	12-26-74
Address: Las Pinas Casimiro	Time Started: 3:22	No. of Contract of	Time Ended:	5:30pm
Contact Person :		4		1
Unit / Description :	INCIDENT No.:	PLS	5-2024 1226	-200768
				100
	de la rial			
Nature of Call/Problem: 105 # 100 6 Monitor was no display	Units/Materials Cor	nplete	Details :	
WITH POWET	SERVICE STATE			
	4、2015年5			AND A
	A CONTRACT STATE		+12个点数据	通知的
Actions Taken:	hi turkeye i	de ala Labora		
Tested power adapter it was not working.				
Replaced Monitor Power adapter of Tosz				
- Configured 15:103 105 #6 1	14 20 1 12	15 m		
Status: Ok	TO THE REAL PROPERTY.			
		Coleto		
TO STATE OF THE PARTY OF THE PA	ATA SOM			734 504
	注中共享 表表			7 19 1 13
	KERTHER.			3.274.95
是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个			3,75 4530	
patrein Patrick Garcia	MAREIZ	Ino	165	

SE's Signature Over Printed Name

End User / Officer's Signature Over Printed Name