

FIELD SERVICE REPORT

FSR NO. 020088903

	OTUEDO.		
SOFTWARE HARDWARE	OTHERS	***	
Customer: TGION	Time Arrived: 1000	Date Attended:	-20-25
Address: Las piñas Talon	Time Started: 10 Pto	Time Ended:	20 25
Contact Person :	7 1044	•) • OOH• •
Unit / Description :	INCIDENT No.:)Ls - 20250120	-20338
		2020-12	-03351
Nature of Call/Problem:	Units/Materials Com	plete Details :	
TOS #1 and Tos#2 1 suki card reader	_		
was unable lored			
VI. S. VI. SEC. S. C. S. V. S.			
Actions Taken:			
checked cable .	-		
- Configured main server to copy 1-Card			
rech Program	-		
tested and observed			
Status: Olc		- Company	
			Magazini
Cotton / Say h.			
SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name		