

## IdeaServ Systems, Inc. 441 Lt. Artiaga St., Brgy. Corazon De Jesus, San Juan City, Philippines Tel. No.: (632) 8415-1174

## FSR NO. 050 0060896

## FIELD SERVICE REPORT

| NO CHARGE CHARGE                      | ASC WARRANTY OTHERS                              |
|---------------------------------------|--|
| Customer: DUNKin Danuts               | Time Arrived: 4:00PM Date Attended: 2-1-25       |
| Address: SMBF                         | Time Started: 4.00PM Time Ended: 6.10PM          |
| Contact Person :                      | Time Linded. 67 [011]                            |
| Unit / Description :                  | INCIDENT No.: APS -20250128-201466               |
|                                       |  |
|                                       |  |
| Nature of Call/Problem:               |  |
| Deliver and install Varipos Mainboard | Units/Materials Complete Details :               |
| TOTAL VIND HEMIT VALLES PRINTERIO     |  |
|                                       |  |
|                                       |  |
| Actions Taken:                        |  |
| Replaced Mother board                 |  |
| Tested and Observed                   |  |
| Status: 01                            |  |
|                                       |  |
|                                       |  |
|                                       |  |
|                                       |  |
|                                       |  |
|                                       |  |
|                                       |  |
|                                       |  |
| DATAN                                 |  |
| Potrick Carcia                        | Kimberlien Padohinog                             |
| SE's Signature Over Printed Name      | End User / Officer's Signature Over Printed Name |
| Authorized Service Provider of: and   |  |
| AP                                    | SOFT   |