

FIELD SERVICE REPORT

FSR NO. 020083237

SOFTWARE HARDWARE	OTHERS		
Customer: MOC (16)	Time Arrived: 2.439	Date Attended:	1-3-25
Address: Jaka Plaza	Time Started: 2.43		3-34 pm
Contact Person :		_	
Unit / Description :	INCIDENT No.: PLS-20250 03-20 626		
	1.37	2.3.27	"公本"
			Section 1
Nature of Call/Problem:	Units/Materials Complete Details :		
ence lenter CPU has no power	The state of the s	學是的意識。	
	No. of the last of		
		" "一个一个	
Actions Taken:		The state of the state of	
Replaced Power adapter			1417C 2 343
Observed and tested			光
Status: OK		· · · · · · · · · · · · · · · · · · ·	THE RESERVE TO THE RE
			V 13 11 10
			AND THE STATE OF
A COLUMN TO SERVICE TO	to the second		
	A TANK TOP TO	· 中国 · 中岛中	TO ADDA
的现在分词 的现在分词的现在分词	A TRANSPORT	10000	
	Sant Marin		
	AND THE		
Patrick Garcia SE's Signature Over Printed Name		· · · · · · · · · · · · · · · · · · ·	Tyrus and
Patrick Garcia	1 上 1 1 1	MATIA	
SE's Signature Over Printed Name	End User / Officer's	Signature Over Printed N	lame