

IdeaServ Systems, Inc.

441 Lt. Artiaga St., Brgy. Corazon De Jesus, San Juan City, Philippines
Tel. No.: (632) 8415-1174

FSR NO. 050 0060884

FIELD SERVICE REPORT

NO CHARGE CHARGE	ASC WARRANTY OTHERS
Customer: (Bldiacts	Time Arrived: 9. Soam Date Attended: 1-22-25
Address: Manual turn Al	Time Started: 0.000Mm Time Ended: 5:08 Pm
Contact Person :	
Unit / Description :	INCIDENT No.: GITSM -32489
Nature of Call/Problem:	Units/Materials Complete Details :
setup of MPC office printer	
Biometrics and Printer	
Actions Taken:	
installed MPC	
installed Biometrics	
11010100 + 11 1 1 1 1 1 1 1 1 1 1 1 1 1	
installed lettonika and fortine! When placed inside cobinet the signal is	
Weak temporary moved Fortinet below	
DOC TEMPORALY POVED TOTALE DOC	
Edward American Color	
Testel and Observed	
Status: OK	
THE PARTY OF THE P	
	A STATE OF THE STA
Patrick Garcia	Joseph Lymber
SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name

Authorized Service Provider of:



and

