

IdeaServ Systems, Inc. 441 Lt. Artiaga St., Brgy. Corazon De Jesus, San Juan City, Philippines Tel. No.: (632) 8415-1174

FSR NO. 010 0204852

FIELD SERVICE REPORT

NO CHARGE CHARGE	ASC WARRANTY OTHERS
Customer: Lawson	Time Arrived: 8:56 PM Date Attended: -13-25
Address: South Station	Time Started: 8:56 PM Time Ended: 9:30 PM
Contact Person :	
Unit / Description :	INCIDENT No.: [DS-20250110-202364
Nature of Call/Problem:	Unite/Metaviele Commiste Date !!-
POS 1 Printer incomplete printout	Units/Materials Complete Details :
The Hole Hillion	
Actions Taken:	
Replaced Printer	
changed Receipt Width to 58 mm.	
Observed and tested	
O SSETTED UIT TOO! O	
Status: OKay	
Patrick Grein	Carpain .
SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name
	Ossi i Gilgitatale Over Pfilited Name
Authorized Service Provider of: TOSHIBA	

Leading Innovation >>>> TOSHIBA GLOBAL COMMERCE SOLUTIONS