

Ideaserv Systems, Inc. 441 Lt. Artiaga St., Brgy. Corazon De Jesus, San Juan City, Philippines Tel. No.: (632) 8415-1174

FSR NO. 010 0204851

FIELD SERVICE REPORT

| NO CHARGE CHARGE | ASC WARRANTY OTHERS |
|---|--|
| Customer: Lawson | Time Arrived: 3:00 PM Date Attended: 1-10-25 |
| Address: Pilar Village | Time Started: 3 - OOPM Time Ended: |
| Contact Person : | TOC 20210110-202296 |
| Unit / Description : | INCIDENT No.: |
| | |
| | |
| | |
| Nature of Call/Problem: | Units/Materials Complete Details : |
| Server Monitor flickering Screen | |
| | |
| | |
| | |
| Actions Taken: | |
| - Replaced Power adapter | |
| RII Testadond Observed | |
| K" ESICONO OLDENES | |
| Status: OK | |
| 01010.00 | |
| UPS sometimes shutsdown while printing | |
| Recommendation Observe if UPS shutsdown | |
| again | |
| | |
| | |
| | |
| Starilles: | (hilist |
| Patrick Gatcia | awa pygirano |
| SE's Signature Over Printed Name | End User / Officer's Signature Over Printed Name |

Authorized Service Provider of:

TOSHIBA

Leading Innovation >>> TOSHIBA GLOBAL COMMERCE SOLUTIONS