

## FIELD SERVICE REPORT

FSR NO. 020089035

SOFTWARE HARDWARE	OTHERS
Customer: MX (199)	Time Arrived: 6:00pm Date Attended: 1-19-25
Address: Muntinlupa Bangaran	Time Started: 6: 00PM Time Ended: 6: 44 PM
Contact Person :	
Unit / Description :	INCIDENT No.: PLS-20250  9-20333
Nature of Call/Problem:	Units/Materials Complete Details :
Backup server Printer was always	
Stack up upon printing	
Actions Taken:	
Replaced Printer	
tested and Observed	
Status: Ok	
	- // fur
Sarea	/ N at
Patrick Garca	End User / Officer's Signature Over Printed Name