

FSR NO. 010 0202402

FIELD SERVICE REPORT

NO CHARGE CHARGE	ASC WARRANTY OTHERS
Customer: PUREGOLD (652) 88 SQUARE	Time Arrived: 9:35 Am Date Attended: 12.03.24
Address: PARATHOUE	Time Started: 9:40 PM Time Ended: 10: 35 AM
Contact Person :	
Unit / Description :	INCIDENT No.: 105. 20241202. 198459
Nature of Call/Problem:	Units/Materials Complete Details :
Lane 4 Customer Display no display always	
Need to set PORT volts to 12 V on BIOS	
Just to Work properly	
Actions Taken:	
Disassembled POS Unit Vari POS 850/51	
Unplugged cables .	
Checkel Chos Battery .	
Note: for Requesting CMOS Battery server	
Replugged all cables	
Assembled POS Unit	
configuration of BIOS Settings	The second secon
Activated Com 3 12 V/test and observed	
Status: Back Job	THE RESIDENCE OF THE PARTY OF T
1964. 6000	
JOHN LUCAS M. LOT / Patrick Jeri L Garcia	Christelli IM Hours which
SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name

Authorized Service Provider of:

TOSHIBA

Leading Innovation >>> TOSHIBA GLOBAL COMMERCE SOLUTIONS