

FIELD SERVICE REPORT

FSR NO. 020088973

SOFTWARE HARDWARE	OTHERS
Customer: MD (Address: ATC Madrigal Contact Person:	Time Arrived: 1.00PM Date Attended: 1-11-25 Time Started: 1.00PM Time Ended: 5.00PM INCIDENT No.: PLS-20250111-202537
Nature of Call/Problem: DOS#3 Monitor has Blinking display	Units/Materials Complete Details :
Actions Taken:	
Replaced Monitor Observed and testes Status: Okay	
Patrick Garcia SE's Signature Over Printed Name	End User / Officer's Signature Over Printed Name